

FW 5.1.5 Build 1 Release Notes – Improvements

The CHeKT Video Control Panel Firmware release notes include new features and bug fixes added since FW version 5.1.4 Build 8. This firmware update is designed to enhance current CHeKT Dealer and Monitoring Portal features, while others are designed to support new features and future portal development.

Notes for Dealers

Dealers should anticipate the firmware update process to take between 5 and 10 minutes, depending on the download bandwidth available on the site. If you notice the process is taking longer, we advise you to allow your video control panel at least one hour before attempting a power cycle or reboot.

Firmware Update Notes

ADDED Support

1. ADDED: Exception handling for an Axis Multilens camera model/firmware that would not present the correct parameters for the device video sources.
 - a. AXIS P3719-PLE Network Camera(FW v11.11.141)
2. ADDED: Exception handling logic for cameras not returning recording events in the Profile G API response.