

FW 3.2.1 Build 1 Release Notes – Bug Fix

The CHeKT Video Bridge Firmware release notes include new features and minor bugfixes added since FW version 3.1.0 Build 5. This Video Bridge firmware update is designed to enhance current CHEKT Dealer and Monitoring Portal features, while others are designed to support new features and future portal development.

Notes for Dealers

Dealers should anticipate the firmware update process taking between 5 and 10 minutes, depending on the download bandwidth available on the site. If you notice the process taking longer, we advise you to allow the Bridge at least one hour before attempting a power cycle or reboot.

Firmware Update Notes

BUG FIXES

1. Fixed Time Sync issue with Axis cameras

IMPROVEMENTS

1. Added EchoData User Data for Arming/Relay/Audio Broadcasts to Cloud.