

FW 2.8.0 Release Notes

Date: 1/8/2021: Released Firmware Ver 2.8.0. The previous released version was 2.7.0

Notes for Dealers

Dealers should anticipate the firmware update process taking between 5 and 10 minutes, depending on the download bandwidth available on the site. If you notice the process taking longer, we advise you to allow the Bridge at least one hour before attempting a power cycle or reboot.

Firmware Update Notes:

FW 2.8.0 is considered a Feature Release that adds additional features to the Bridge and the CHeKT Platform. The following items were corrected and added in 2.8.0

BUG FIXES

- Fixed ONVIF Mounting issues and ONVIF Analytic event issues with Bosch series cameras. In previous versions, of the Bridge FW, a mounted Bosch camera would disconnect from the Bridge every 3 minutes if the channel was programmed to create event triggers from the Bosch camera analytic IVS information.

IMPROVEMENTS:

- Added support AXIS IP Audio Devices.
 - With FW version 2.8 the each Bridge supports up to four IP Audio channel for transmitting On-Demand or Live talk down messages to an AXIS IP Audio Device.
 - This feature was validate with the AXIS IP Speakers and the AXIS C8033 IP Audio Bridge.