

FW 3.4.0 Build 6 Release Notes – Feature Release

The CHeKT Video Bridge Firmware release notes include new features and minor bug fixes added since FW version 3.2.1 Build 1. This Video Bridge firmware update is designed to enhance current CHEKT Dealer, and Monitoring Portal features, while others are designed to support new features and future portal development.

Notes for Dealers

Dealers should anticipate the firmware update process to take between 5 and 10 minutes, depending on the download bandwidth available on the site. If you notice the process taking longer, we advise you to allow the Bridge at least one hour before attempting a power cycle or reboot.

Firmware Update Notes

New Features

1. Live Audio Voice Talk Down from the CHeKT Monitoring Portal and End User Mobile App.
2. Added Support for ONVIF Compatible IP Audio Devices. (IP Speakes & Cameras w\Speakers)
3. Added Support for Local API Event Recording Requests to the Bridge.

IMPROVEMENTS

1. Increased Snapshot Size Limit during camera mounting test.
2. Adjusted Watchdog sensitivity on DIDO DaemonMonitoring.
3. Adjusted GetDIStatus retries attempts and intervals.