

Field Impact Notice

Document Date: December 2025

Summary

Following an upgrade to CHeKT camera firmware **v.65**, existing *loitering time configuration data* is deleted.

While loitering time settings can be manually re-entered after the upgrade, all previously configured values are lost.

Required Conditions Present

- CHeKT Camera is running, or had been previously updated to firmware version v.65
- Loitering time configuration is present prior to upgrade, but loitering time has been removed

Resolution

Do **not** upgrade any camera with existing loitering time configuration to firmware v.65. Firmware **v.66** will allow upgrades without removing saved loitering time settings.

For devices already running v.65:

- Loitering time settings must be manually reconfigured.
- Manually re-entered settings will persist through the upgrade to v.66.

For devices downgraded from v.65 to v.61:

- Loitering time settings must be manually reconfigured.
- Manually re-entered settings will persist through the upgrade to v.66.