

FW 4.3.0 Build 3 Release Notes – Minor Release

Date: 12 August 2024

The CHEKT Video Bridge Firmware release notes include new features and bug fixes added since FW version 4.3.0 Build 2. This Video Bridge firmware update is designed to enhance current CHEKT Dealer and Monitoring Portal features, while others are designed to support new features and future portal development.

Notes for Dealers

Dealers should anticipate the firmware update process to take between 5 and 10 minutes, depending on the download bandwidth available on the site. If you notice the process taking longer, we advise you to allow the Bridge at least one hour before attempting a power cycle or reboot.

Firmware Update Notes

BUG FIXES

1. **FIXED:** On some automated audio events, the audio file was not playing all the way to the end. Dealers were experiencing the audio cut off about 2 seconds before the end of the message.